




## Simpson Performance Products

### Snell 2015 SA Voyager 2 Helmet Recall (Sizes Extra Small - Large with manufacturing dates in 2016)



Snell SA 2015 Voyager 2 Helmet



Sample Snell SA 2015 Label

**SAFETY & RECALL NOTICE  
TO DISTRIBUTORS, DEALERS & CONSUMERS**

Simpson Performance Products  
Snell SA 2015 Certified Voyager 2 Helmet Recall

TO: All Simpson Distributors, Dealers and Consumers  
FROM: Simpson Performance Products, New Braunfels,  
Texas USA  
Date: April 6, 2017

Simpson Performance Products has recently discovered a potential safety issue with its Snell SA 2015 Voyager 2 helmet. The chin strap could detach from one or both sides of the helmet. This presents an enhanced risk of injury to the head should the helmet not be retained in a crash. Simpson Performance Products is voluntarily recalling the Snell SA 2015 Voyager 2 helmet due to a potentially weak chin strap. The problem was discovered during testing with the Snell Foundation. We stress that no problems have been reported from the field in nine months of use but in the interest of racing safety, we are proactively recalling these products and providing our customers with a safe resolution. This recall applies to the Snell SA 2015 Voyager 2 Model only, sizes Extra Small – Large (the only sizes sold and available to date). It does NOT apply to any other Simpson helmet models with Voyager in the name, i.e. NOT Snell SA 2010 Voyager or Snell SA 2010 Sidewinder

Voyager, etc. It is only the Snell SA 2015 Voyager 2 helmet as pictured here.



Reference:  
Snell Internal Certification Number

As a quick self-check to verify that your Voyager 2 is involved in this recall, refer to the two Snell Internal Certification Number Labels show above and match one of those numbers to the internal label found sewn on the inside of your helmet, on the side of the size label.